



XTech Gear, Inc. is able to provide testing and repair services for all Cisco / Cerent ONS 15454 equipment. We currently have 4 15454 Shelves configured in a ring formation as well as line and signal testing equipment, allowing us to ensure that Optical, Electrical, Ethernet and Control circuit packs are functional and operating properly.

All equipment that enters our facility for testing or repair is entered into our equipment tracking system, and the board's status is updated as our technicians go through testing procedures on the circuit pack. You are able to check the status of your equipment at any time via our web based Repair Portal, or by contacting one of our repair representatives.

Here is a listing of board we routinely repair. Please note that repair costs are associated with the manner of the problem, and while we are able to generally provide a rough estimate, a complete estimate will not be able to be issued until we are able to test the circuit board in our internal labs.

- OC192 LR 1550
- OC192 IR 1550
- OC192 LR2
- OC192 IR 1310
- OC192 LR 1310
- OC192 ELR 15XX
- OC192 SHORT REACH
- OC48 IR 1310 A
- OC48 LR 1550 A
- OC48 IR 1310
- OC48 LR1310

- OC48 IR 1550
- OC48 LR 1550
- OC48 ELR 15XX
- OC3 IR 4 1310
- O12 IR 4 1310
- OC12 IR 1310
- OC12 IR 1550
- OC12 LR 1310
- OC12 LR 1550

- TCC2
- TCC2P
- TCC2P K9
- TCC+
- TCC
- XC VT
- XC 10G
- XC VXL 10G
- XC VXC 10G
- XC
- AIC
- AIC-I
- FTA3 T
- FTA2
- FTA
- 15454 ANSI
- 15454 NEBS3
- 15454 NEBS3E
- 15454HD

- DS3N 12
- DS3 12
- DS3N 12E
- DS3 12E
- DS3 XM6
- DS3 XM12
- DS1 14
- DS1N 14
- DS1I 14
- E100T 12
- G1000 4
- G1K 4
- E1N 14
- E1000 2

- EC1 12
- M4000 2
- M400T 12
- ML100T 12
- ML100X 8
- MRC 12

- EIA BNC A48
- EIA BNC B48
- EIA AMP A84
- EIA AMP B84
- EIA SMB A84
- EIA SMB B84
- EIA 1BNC B48
- EIA 1BNC A48
- EIA BNCA96
- EIA BNCA96
- EIA BNC B24
- EIA BNC A24

If you have any additional questions, please feel free to [contact us](#)

This e-mail address is being protected from spam bots, you need JavaScript enabled to view it

This e-mail address is being protected from spam bots, you need JavaScript enabled to view it