



XTech Gear, Inc. is able to provide testing and repair services for all Calix C7 MSAP equipment. We currently have 2 C7 shelves configured in a ring formation as well as line and signal testing equipment, allowing us to ensure that Optical, Electrical, Ethernet and Control circuit packs are functional and operating properly.

All equipment that enters our facility for testing or repair is entered into our equipment tracking system, and the board's status is updated as our technicians go through testing procedures on the circuit pack. You are able to check the status of your equipment at any time via our web based Repair Portal, or by contacting one of our repair representatives.

Here is a listing of board we routinely repair. Please note that repair costs are associated with the manner of the problem, and while we are able to generally provide a rough estimate, a complete estimate will not be able to be issued until we are able to test the circuit board in our internal labs.

- 000-00043
- 100-00016
- 100-00343
- 100-00097
- 100-00116
- 100-00126
- 100-00135

- 100-00143
- 100-00180
- 100-00330
- 100-00358
- 100-00360
- 100-00413
- 100-00428
- 100-00482
- 100-00489
- 100-00498

- 100-00514
- 100-00681
- 100-00682
- 100-00683
- 100-00684
- 100-00685
- 100-00686
- 100-00687
- 100-00688
- 100-00698
- 100-00690
- 100-00692
- 100-00695
- 100-00696
- 100-00699
- 100-00701
- 100-00702

- 100-00705
- 100-00746
- 100-00126
- P97-10069
- P97-10157
- P97-10158
- P97-10472-09
- p97-9421
- S3EES03
- S3EES06
- 100-00022
- 100-00014
- 100-00143
- 100-00574
- 100-00181

- 100-00330
- 100-00020

- 100-00215
- 100-00143
- 100-00167
- 100-00220
- 100-00007
- 100-00009
- 100-00021
- 100-00143
- 100-01329
- 100-00253
- 100-00482
- 100-00456
- 100-00574
- 100-00593
- 100-00018
- PS-1100-02
- PS-1100-03

If you have any additional questions, please feel free to [contact us](#)

This e-mail address is being protected from spam bots, you need JavaScript enabled to view it

This e-mail address is being protected from spam bots, you need JavaScript enabled to view it